PEPKEI

PRINTY

Office

iar File

QUT55783

P 200022Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 4580.

1965 MAY 20 OO 39 Z

15TH AF (FOR DI), SAC (FOR DIM/GOLD TREE/DOCR, DM 4) 2D AF (FOR DI) COPIES RECEIVED

- 1. CAMERA B 101 WAS USED IN MISSION 8017 FLOWN ON 18 MAY 1965 Oylio.

 PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.
 - 2. ORIGINAL NEGATIVE:

AN INTERMITTENT MAJOR SHUTTER MALFUNCTION OCCURRED DURING THE

MISSION. AVAILABLE EVIDENCE INDICATES POSSIBLE MISLATCHING. THE

SHUTTER REMAINED OPEN APPROXIMATELY 85 PERCENT OF THE TIME CAUSING 4 FOR THE SHUTTER REMAINED CLOSED OF THE PERCENT OF THE MISSION IS BLANK WHERE THE SHUTTER REMAINED CLOSED OF THE MISSION IS BLANK WHERE THE SHUTTER REMAINED CLOSED OF THERE ARE A TOTAL OF 168 FRAMES ON EACH SIDE WHICH ARE USEABLE OR PARTIALLY USEABLE. THE IMAGERY ON THESE FRAMES IS SOFT, APPARENTLY Destroyed

DUE TO A VACUUM FAILURE. THE FIRST USEABLE FRAME BY COUNTER NUMBER

3. POSITIVE:

IS 77 AND THE LAST IS 2213.

- A. THE PI SUITABILITY IS POOR.
- B. ONLY THE 168 USEABLE FRAMES WERE REPRODUCED.
- C. IT IS RECOMMENDED THAT THIS CAMERA NOT BE USED UNTIL CORRECTIVE MAINTENANCE IS UNDERTAKEN.

SECRET

/END OF MESSAGE/

GROUP 1
Excluded from automatic
downgrading and
declassification